

석면해체.제거작업사업장 석면비산측정결과보고서

측정대상 : 부산광역시 남구 용주로22번길 1
외 13개 지번

측정일자 : 2019. 03. 01.(71차)

6-1. <측정결과>

측정위치	측정시간(분)	유량(ℓ/min)	측정농도(개/ cm^3)	초과여부
P-1 (부지경계선1)	09:28~12:08 (160분)	15.8	0.0013	미만
P-2 (부지경계선2)	09:35~12:15 (160분)	15.6	0.0014	미만
P-3 (부지경계선3)	09:41~12:21 (160분)	15.7	0.0015	미만
P-4 (부지경계선4)	09:48~12:28 (160분)	15.2	0.0014	미만
P-5 (거주자주거지역1)	09:55~11:15 (80분)	15.5	0.0014	미만
P-6 (거주자주거지역2)	09:58~11:18 (80분)	15.4	0.0012	미만
P-7 (작업장주변실외)	10:04~11:24 (80분)	15.7	0.0010	미만
P-8 (위생설비입구)	10:09~10:39 (30분)	15.6	0.0010	미만
P-9 (폐기물반출구1)	10:31~11:01 (30분)	15.4	0.0016	미만
P-10 (폐기물반출구2)	11:13~11:43 (30분)	15.3	0.0010	미만
P-11 (폐기물반출구3)	14:40~15:10 (30분)	15.5	0.0016	미만
P-12 (폐기물보관지점1)	14:49~15:19 (30분)	15.8	0.0010	미만
P-13 (폐기물보관지점2)	14:57~15:27 (30분)	15.4	0.0011	미만
P-14 (폐기물보관지점3)	15:12~15:42 (30분)	15.3	0.0011	미만

6-3. <측정위치>



6-4. <시료채취사진>-1

시료번호	P-1	P-2	P-3	P-4
시료채취사진				
장 소	부지경계선1	부지경계선2	부지경계선3	부지경계선4

시료번호	P-5	P-6	P-7	P-8
시료채취사진				
장 소	거주자주거지역1	거주자주거지역2	작업장주변실외	위생설비입구

6-4. <시료채취사진>-2

시료번호	P-9	P-10	P-11	P-12
시료채취사진				
장 소	폐기물반출구1	폐기물반출구2	폐기물반출구3	폐기물보관지점1

시료번호	P-13	P-14
시료채취사진		
장 소	폐기물보관지점2	폐기물보관지점3

석면해체·제거작업사업장 석면비산측정결과보고서

측정대상 : 부산광역시 남구 용주로22번길 1
외 13개 지번

측정일자 : 2019. 03. 02.(72차)

6-1. <측정결과>

측정위치	측정시간(분)	유량(ℓ/min)	측정농도(개/ cm^3)	초과여부
P-1 (폐기물반출구1)	09:02~09:32 (30분)	15.4	불검출	미만
P-2 (폐기물반출구2)	09:10~09:40 (30분)	15.1	불검출	미만
P-3 (폐기물반출구3)	09:17~09:47 (30분)	15.6	0.0010	미만

6-3. <측정위치>



6-4. <시료채취사진>

시료번호	P-1	P-2	P-3
시료채취사진			
장 소	폐기물반출구1	폐기물반출구2	폐기물반출구3